



Clean your world.

**CORBETT SCHOOL DISTRICT
SUMMARY OF DAMAGED ASBESTOS-CONTAINING MATERIALS
September 26, 2020**

The condition of the asbestos-containing materials in the District is generally good. This sheet for your use in locating and/or addressing materials that were observed to be damaged, or had substantial changes since the 2017 re-inspection.

High School

- All assumed ACM appears to be in good condition.

Middle School

- There is damaged plaster ceiling in the basement that tested negative for asbestos.
 - It is recommended that additional sampling be performed prior to evaluating that all plaster within the building is NON-ACM.
- There is damaged stair treads that area assumed to have asbestos mastic.

Multipurpose Building

- All assumed ACM appears to be in good condition.

PE & Gym

- Girls locker room has gold 12X12 floor tile that has approximately 6sqft of damage.
 - It is recommended that this material be assumed to be asbestos until tested and the tile repaired.
- There are damaged har fittings in the back gym, weight room, and team room.
 - The fittings are assumed to contain asbestos and should be repaired or removed by a licensed abatement contractor.

The past 3-year reviews that have been performed for Corbett School District seem to be lacking many materials on the inspection plan. It is advised that the next inspection have more detailed plans.